

CASE STUDY

Waterproofing of Basement Floor Cracks and Joint Treatment

Wings Court (2016)

BACKGROUND

There were leakages in the car park emanating from cracks and construction joints in basement floor slab.

SOLUTION

The joints/ cracks were treated using our joint/ crack repair system. While the surfaces were treated using our Krystol T1/T2 surface application treatment.

**PROJECT:**

Basement Floor Cracks and Joints Treatment

CLIENT:

Cappa & D'Alberto

**DISTRIBUTOR/
APPLICATOR:**

Concrete Logistics Limited

**PRODUCTS & TECHNICAL
SPECIFICATION:**

Krystol Crack/Joint Repair
System Krystol T1/T2